

GOLDEN SUNLIGHT MINES, INC.

453 Montana Hwy 2 East
Whitehall, Montana, USA, 59759

22 May 2006

Daniel Journeaux
Janod Contractors
190 Valois
Vaudreuil-Dorion, QC
J7V 1T4


Subject: Mitigation of the GSM Fenner Block Rock Fall Hazards

Dear Daniel:

I wanted to thank you and the Janod crews for a job well done in the removal of the Fenner Block rock fall hazards. This was a difficult job requiring good planning and coordination of men, equipment, and materials. When we ran into a few unexpected difficulties that pushed out our schedule, your men adjusted to the situation well, and were still able to finish the work before the end of the year, despite some harsh weather conditions. Since you installed the ring net barrier, we experienced a record setting precipitation event that resulted in a number of large rocks releasing in the Fenner Fault chute. The ring net barrier worked as planned.

I would especially like to acknowledge your supervisor, Noel Philippon, for insuring efficient operations of your crews and integrating his efforts with our mine operations. Janod did a great job for GSM and will be considered for future GSM jobs that require this unique expertise.

Sincerely,



Tim Dimock
Mine Superintendent

TEL (406) 287-3257 FAX (406) 406-287-2035
DIRECT (406) 406-287-2046
EMAIL tdimock@barrick.com